



Stock Image



®

www.JetAdvisors.com | +1.617.600.6990

1985 Hawker 800B

1985 Hawker 800B | \$890,000

G-IFTF | 258021
 Total Time: 12,333
 Total Landings: 8,089

	Engine 1	Engine 2
	Honeywell TFE 731-5R-1H	
Serial Number	P91226	P91143
Total Time:	8,477	11,801
Total Cycles:	6,159	7,770
	APU	
	Garrett GTCP30-92C	
Serial Number	P29074	
Total Time:	7,652	

Aircraft Highlights:

- Engines and APU not on MSP
- Enrolled on CAFAM
- Certifications: EASA, MNPS, RVSM
- Due Maintenance - Routine Inspections
- E Inspection (12 Mths) – 21st June 2018
- F Inspection (24 Mths) – 29th June 2018
- G Inspection (48 Mths) – 8th July 2018
- B Inspection (800 Hrs) – 800 Hrs to go
- C Inspection (1600 Hrs) – 1600 Hrs to go



Avionics/Radios:

- TCAS 7.1 Compliant
- Honeywell MK VIII EGPWS
- Honeywell Class B TAWS
- Collins Five Tube EFIS 86C
- Dual Collins VIR-32 Navs
- Dual Collins VHF-22B Comms
- Dual Collins EFD-85 Flight Directors
- Dual Collins TDR-90 Transponders
- Dual Collins Air Data Computers
- Dual Universal UNS-1Msp FMS
- Dual King-956 HF Comms w/ SELCAL
- Collins APS-85B Autopilot
- Collins DME-42
- Collins ADF-60B
- Collins ALT-55B Altimeter
- Collins WXP-85 Color Radar
- Collins ALT-55B Radar Altimeter
- Trimble 2000 GPS
- SAT/AFIS
- Multi-Function Display

Additional Equipment:

- 8.33 / FM Immunity Compliant
- Aircell/Iridium 2HS Satcom
- CVR PN: S100-0080-00 (Model: A100S)
- FDR PN: 650-1-14040-010 (Model: PV1584A)
- Dual Davtron Clocks
- Dual Baker M-1045 Audio Amplifiers
- Lead Acid Batteries
- Dual ADS-80 Air Data System
- Marconi AD-1550 Audio System
- Dual MC-103 Compass
- FPA-80 Wiring/Space Provisions
- RVSM & MNPS
- Stereo Radio CD
- FD932 DVD Player
- Airshow FD200 Moving Map

Interior: The aircraft has a capacity of 8 passengers in 5 individual seats and 1 three seat sofa, with a newly refurbished interior. The aircraft features a stand up cabin, separate baggage compartment, hot galley and bar, partition door between the galley and cabin for passenger privacy, as well as separate bathroom facilities to ensure the highest levels of comfort throughout the flight.





www.JetAdvisors.com

subject to verification by buyer

Jet Advisors, LLC | Kevin O'Leary Ph.D.
Hanscom Field | +1.617-600-6868
200 Hanscom Drive, Suite #301 | +1.617.600.6990
Bedford, MA 01730 | koleary@jetadvisors.com



www.JetAdvisors.com

subject to verification by buyer

Jet Advisors, LLC | Kevin O'Leary Ph.D.
Hanscom Field | +1.617-600-6868
200 Hanscom Drive, Suite #301 | +1.617.600.6990
Bedford, MA 01730 | koleary@jetadvisors.com



www.JetAdvisors.com

subject to verification by buyer

Jet Advisors, LLC | Kevin O'Leary Ph.D.
Hanscom Field | +1.617-600-6868
200 Hanscom Drive, Suite #301 | +1.617.600.6990
Bedford, MA 01730 | koleary@jetadvisors.com



Stock Image

www.JetAdvisors.com

subject to verification by buyer

Jet Advisors, LLC	Kevin O'Leary Ph.D.
Hanscom Field	+1.617-600-6868
200 Hanscom Drive, Suite #301	+1.617.600.6990
Bedford, MA 01730	koleary@jetadvisors.com